
High Level Sewershed

Run Summary —					Ground	Notification		
Test ID	Test Type	Date Inspected	Company / Super.	Nearest MH	Condition	Made?	1	
D1028-165	Dye	4/23/2009	ADS/TM	S13EE1016MH	Damp	NA		
Address 400	00 Pimlico Road		Location	Curb	Status P	ublic	Source	Catch Basin



High Level Sewershed

Run Summary								
Test ID	Test Type	Date Inspected	Company / Super.	Nearest MH	Ground Condition	Notification Made?	1	
D1028-165	Dye	4/23/2009	ADS/TM	S13EE1016MH	Damp	NA		
Address 400	0 Pimlico Road		Location	Curb	Status Po	ublic	Source	Catch Basin

Observations & Photos

Obs_ID D1028-165-OB01 **Nearest MH** S13EE1016MH

Comments Dye observed 3.0 ft. downstream of S13EE1016MH.

Infiltration runner at joint at 10 oclock.

Obs_ID D1028-165-OB02

Nearest MH S13EE1016MH

Comments Dye observed 11.5 ft. downstream of

S13EE1016MH. Infiltration runner at joint at 9 oclock





Picture \D1028-165-OB01-P01.jpg

Comments 3.0 ft. downstream of S13EE1016MH along

S13EE1016G1.

Picture \D1028-165-OB02-P01.jpg

Comments 11.5 ft. downstream of S13EE1016MH along

S13EE1016G1.



Thursday, May 28, 2009

Page 2 of 4

High Level Sewershed

Run Summ	Run Summary —							
Test ID	Test Type	Date Inspected	Company / Super.	Nearest MH	Ground Condition	Notification Made?	l	
D1028-165	Dye	4/23/2009	ADS/TM	S13EE1016MH	Damp	NA		
Address 400	00 Pimlico Road		Location	Curb	Status Po	ublic	Source	Catch Basin

Obs_ID D1028-165-OB03

Nearest MH S13EE1016MH

Comments Dye observed 18.0 ft. downstream of

S13EE1016MH. Infiltration runner at joint at 10

oclock.

Obs_ID D1028-165-OB04 **Nearest MH** S13EE1016MH

Comments Dye observed 20.5 ft. downstream of S13EE1016MH. Infiltration runner at joint at 5

oclock.





Picture \D1028-165-OB03-P01.jpg

Comments 18.0 ft. downstream of S13EE1016MH along

S13EE1016G1.

Picture \D1028-165-OB04-P01.jpg

Comments 20.5 ft. downstream of S13EE1016MH along

S13EE1016G1.

Thursday, May 28, 2009

Page 3 of 4

High Level Sewershed

Run Summ	ary 	Date Inspected	Company / Super.		Ground	Notification		
Test ID	Test Type			Nearest MH	Condition		1	
D1028-165	Dye	4/23/2009	ADS/TM	S13EE1016MH	Damp	NA		
Address 400	00 Pimlico Road		Location	Curb	Status P	Public	Source	Catch Basin

Obs_ID D1028-165-OB05 **Nearest MH** S13EE1016MH

Comments Dye observed 20.5 ft. downstream of

S13EE1016MH. Infiltration runner at joint at 8

oclock.



Picture \D1028-165-OB05-P01.jpg

Comments 20.5 ft. downstream of S13EE1016MH along

S13EE1016G1.